


Dusty Strings

Makers of Harps and Hammered Dulcimers

3450 16th Ave. W., Seattle, WA 98119 • 206-634-1656 • Fax 206-691-3712 • www.dustystings.com

D500 String Chart

for instruments before serial #13169



All strings are loop end. Wire gauges are shown in inches.
 PB indicates phosphor bronze wire. PBW indicates phosphor bronze wound.
 SSW indicates stainless steel wound. Unspecified strings are plain steel wire.

● Indicates marked course. Small numbers indicate octaves (C⁴ is middle C).

The serial number can be found on a tag inside the soundhole.

Rev. 11-25-2014