

Dusty Strings

Makers of Harps and Hammered Dulcimers

3450 16th Ave. W., Seattle, WA 98119 • 206-634-1656 • Toll Free 866-634-1656 • Fax 206-691-3712 • www.dustystings.com

PD30 Stringing Diagram



All strings are loop end. Wire gauges are shown in inches.

■ and □ indicate white and black bridge markers.

PB indicates phosphor bronze.

PBW indicates phosphor bronze wound.

All other strings are plain steel.

Superscript numbers indicate octaves. C⁴ is middle C.